FIRE SAFETY CERTIFICATE

TO WHOM SO EVER IT MAYCONCERN

APPENDIX - L

FORM "S" (SEE RULE 88 (5))

Fire Audit Report

Year 2024

To,

M/S SARASWATI VIDHYA MANDIR HIGHHER SECONDARY SCHOOL MANDSAUR, DISTRICT-MANDSAUR (M.P.)

Address of the Building - JAGAKHEDI ROAD , MANDSAUR ,DISTT. MANDSAUR (M.P.)

Sir,

Sub: Submission of Fire Certificate No.-

IND/FSC/003/2024

Date of Issue - 24.06.2024

Date of Expiry -23.06.2025

THIS CERTIFICATE IS ISSUED AS PER THE MADHYA PRADESH UADD BHOPAL LETTER NO.981/895002/2022/18-3 ON DATED 16.12.2022.

I AM **ER. VINOD SONI** have inspected your building / premises on **24**th **JUNE- 2024** and checked all Fire Equipment's /installations and have completed The fire Audit of the said Building / premises of **SARASWATI VIDHYA MANDIR HIGHHER SECONDARY SCHOOL MANDSAUR**, **DISTRICT-MANDSAUR** (M.P.)

According to the use and character of occupancy; the campus includes building as **"EDUCATIONAL BUILDING"** Plot area of the building is 2705 sq. Mtr. and Height of the Building Premises (12 MTR)

2. Details of fire system installed are as below: -

| S.N | Particular | Available/installed or | Comments for |
|-----|-------------------------------------|--|---|
| o | | not installed(as per | working of System |
| • | | requirements) | (Attach detail, if any) |
| 1. | Access | (Give comments) Available | In front of Main Road |
| •• | Access | Available | III II OII OI IVIAIII ROdd |
| 1. | Wet Riser | Not Required | Fire fighting installation As per NBC -2016 |
| 2. | Down Comer | Available | |
| 3. | Hose Reel | Available | Hose reel hose has been installed every floor if in case any fire emergency happened in school premises, it can be easily handle with help of hose reels hose |
| 4. | Automatic Sprinkler System | Not Required as per the | Not Installed at as per the |
| | | NBC2016PART IV TABLE NO 7 | NBC-2016 PART IV TABLE NO 7 |
| 5. | Yard Hydrant | Available | Available |
| 6. | Underground Tank | Available | 20 kl underground tank |
| | with Draw off | | available |
| _ | connection | A 'I . I . /40 . //) | 401/1 |
| 7. | Terrace Tank | Available (10 KL) | 10KL tank available |
| 8. | Fire Pump | Not Required as per the NBC2016PART IV TABLE | |
| 9. | Terrace Pump | NO 7 Available | 450 LDM (torrace Dump) |
| | · | | 450 LPM (terrace Pump) AS PER IS 2190 |
| 10 | First Aid Fire Fighting | Available | Ground Floor -ABC Powder Type |
| • | Appliances | | 9 Kg - 4 nos & 4 Kg |
| | пришнеез | | 4 1103 CC 4 11G |
| 11 | Pressurization System | NR | Naturally Ventilated |
| 12 | Auto Detection System | Not available | |
| 13 | Manual Operated Electrical | Available | Manual call Point & hooter |
| • | Fire Alarm System | | Installed |
| 14 | P.A. System with talk back facility | Not Required as per the NBC2016PART IV TABLE | |
| | | NO 7 | |
| 15 | Emergency Light | Available | |
| 16 | Auto D.G. Set | Available | |

| 17 | Illuminated Exit Sign | Not Available | Need to be providing illuminated type. |
|---------|--|---|---|
| 18 | Means of Escape | Available | |
| 19 · | Compartmentation | Not Required as per the NBC2016PART IV TABLE NO 7 | |
| 20 | MCB/ELCB | Available | All floors separate distribution board are there with MCB |
| 21 | Fireman Switch in Lift | Available | Available |
| . 22 | Hose Boxes with Delivery hose and Branches | Not available | |
| 23 | Refuge Area | Available | |
| 24 | Any other installation | | |

भवन अनुज्ञा में लिखित सभी शर्तों को मान्य करना अनिवार्य होगा।

आवेदक / स्वामी को प्रदाय किया जा रहा फायर सुरक्षा प्रमाण—पत्र (FIRE SAFETY CERTIFICATE) जारी दिना क से 01 वर्ष की अवधि के लिये प्रभावशाली रहेगा और यह अवधि समाप्त होने के 01 माह पूर्व प्रमाण—पत्र नवीनीकरण हेतु पुनः आवेदन प्रस्तुत करना अनिवार्य होगा एवं प्रत्येक वर्ष FIRE SAFETY CERTIFICATE के दिनांक से 01 माह पूर्व यह वचन पत्र प्रस्तुत करना होगा कि सभी उपकरण सुचारु रुप से कार्य रहे है।

भवन का स्थल निरीक्षण नियमानुसार भवन मालिक/भवन कर्मचारी/संस्था मैनेजर/संस्था के कर्मचारियों की उपस्थिति में उपकरणों को संचालित करवाकर किया गया है। निरीक्षण के दौरान FIXED FIRE FIGHTING INSTALLATION / FIRST AID FIRE FIGHTING व्यवस्था स्थल निरीक्षण के समय निर्धारित मापदण्ड अनुसार पाई गई है। जिसका स्पष्ट उल्लेख ऑडिट रिपोर्ट में किया गया है। निरीक्षण में FIXED FIRE FIGHTING INSTALLATION नेशनल बिल्डिंग कोड 2016 भाग 04 सेफ्टी के प्रावधानों अनुसार स्थापित किये गये है।

आवेदक को फायर सेफटी हेतु नेशनल बिल्डिंग कोड 2016 भाग 04 में निर्धारित प्रावधानो एवं निर्धारित आईएसआई मानकों का पालन करना अनिवार्य होगा। स्थल निरीक्षण में इन प्रावधानों जैसे— नेशनल बिल्डिंग कोड 2016 भाग 04 एवं ISI मापदंड का पालन न पायें जानें पर फायर सुरक्षा प्रमाण—पत्र (FIRE SAFETY CERTIFICATE) स्वतः निरस्त हो जावेगा।

आवेदक को नियमानुसार स्थापित अग्निशमन उपकरणों का निर्धारित आईएसआई मानकों के अनुसार प्रावधानित समयसीमा में संधारण करना एवं संधारण हेतु आवश्यक अर्हताधारी कर्मचारी रखना अनिवार्य होगा।

दिनांक 30 जून से पहले प्रति वर्ष अग्नि सुरक्षा ऑडिट कराकर अग्नि विभाग में प्रस्तुत करना अनिवार्य होगा।

दिनांक 30 जून से पहले विद्युत सुरक्षा विभाग से प्रति वर्ष इलेक्ट्रिकल सेफ्टी ऑडिट कराकर संबं धित डिपार्टमेंट का` प्रस्तुत करना होगा।

भवन अनुज्ञा प्रमाण-पत्र म.प्र. भूमि विकास नियम 2012 के अंतर्गत कोई भी त्रुटि पाए जाने पर संबंधित विभाग को इस प्रमाण-पत्र को तत्काल प्रभाव से निरस्त करने का अधिकार होगा।

भविष्य में किसी भी प्रकार की आगजनी की अप्रिय घटना घटित होती है, तो इसके लिये स्वंय भवन स्वामी जिम्मेदार होंगे। अन्य कोई नही।

भवन में स्थापित अग्निशमन उपकरण के संचालन हेतु समय ≤ पर भवन में मोकड्रिल एवं कार्यरत् कर्मचारियों का प्रशिक्षण करवाना होगा एवं FIRE EXTINGUISHER REFILLING आदि की व्यवस्था समय ≤ पर निर्धारित रुप से करवाना होगी।

यदि उपरोक्त शर्तो का पालन न हाने पर यह फायर सुरक्षा प्रमाण-पत्र (FIRE SAFETY CERTIFICATE) स्वतः निरस्त हो जावेगा।

